

SABRE 42 SEDAN

MODEL YEAR 2008 OPTIONS

EXTERIOR AND DECK	Part #
Teak coamings in cockpit in lieu of fiberglass	VX0016
Teak decking on FRP swim platform	VX0057
Teak grab rail package in lieu of stainless steel	VX0005
Teak grate command bridge table in lieu of standard	VX0013
Teak decking in cockpit	VX0055
Teak anchor platform in lieu of fiberglass	VX0014
Teak doors on cockpit wet bar	VX0070
Extended Hard top	VX0066
Delete Fly Bridge and fill aft end of cabin house	VX0080
Fiberglass Radar mast for hard top when bridge is deleted	VX0059
Mar Quipt MarQ8 800lb Hydraulic low profile dinghy davit on hard top extension	VX0071
Force 10 propane grill in cockpit wet bar with FRP cover	VM0062
Pompanette P2000T seats in lieu of standard	VX0061
Stidd helm chairs in lieu of standard Pompanette	VX0072
Freestanding motoryacht mast w/radar bracket and tabernacle, spreaders and lights	VX0008
ELECTRICAL	
Additional 12 volt DC outlet (ea. One standard at upper helm)	VE0001
Additional dimmer switches (ea) Specify locations	VE0024
Clarion CD/FM/AM stereo with four speakers and remote control	VE0003
Prewire for stereo and four speakers	VE0004
TV/telephone inlet w/two interior outlets. Specify locations	VE0022
Heart inverter with remote controller	VE0016
Glendinning cord reel with remote for 50 Amp cord set	VE0021
Ice maker installed in cockpit wet bar	VM0019
Freezer AC only Sub Zero under 2nd cabin hanging locker	VE0027
Taylor AC/DC freezer in hanging locker	VE0036
Combo washer/dryer installed under forward cabin berth	VM0040
FIBERGLASS	
Light hull & deck colors other than Sport Yacht White and Sabre White	VX0001
Dark hull colors	VX0002
Anti-skid color (fore & side deck, aft cockpit, coamings, recessed area of swim platform and hard top)	VX0019
INTERIOR/WOOD	
Galley up version with two heads/one shower, two chairs in salon	VI0052
Island Double layout forward	STD
Hinged top on island berth with gas struts	VI00
Hand rail on overhead in main salon	VI0051
Mirrors inside top and bottom of head door to master stateroom (inside head)	VI00
25" Steelcase Barrel chair. Specify fabric choice	VI0050
Curtain tracks Only	VI0002
Curtains (does not include windshield curtains)	VI0003
Curtains (main salon only, does not include windshield)	VI00
Accord Shades on all opening ports	VI0006
Corian counter in galley	VI0011
Ultrasuede upholstery (main cabin and helm seat only)	VI0016
Ultraleather (main cabin and helm seat only)	VI0049

MECHANICAL	
Cummins 500 hp QSC 8.3M engines in lieu of Yanmar 440 6LY includes Smartcraft displays. Includes synchronizer and ETS controls (includes the Groco engine intake valve w/quick release plug and service adapter)	VM0702
Cummins 550 hp QSC 8.3M engines in lieu of Yanmar 440 6LY includes Smartcraft displays. Includes synchronizer and ETS controls (includes the Groco engine intake valve w/quick release plug and service adapter)	VM0704
Yanmar 6LY3-ETP 480 hp electronic engines in lieu of standard 440 Yanmar.	VM0703
Fuel polishing system	VM0075
Reverso Oil Change system	VM0006
Side Power bow thruster Model SP75T	VM0060
Groco engine intake valve w/quick release plug & service adapter.	VM0018
NAVIGATIONAL ELECTRONICS	
Autopilot Ray Marine ST6002G Dual station	VE0020
Searchlight with twin controls	VE0008
PLUMBING	
Incremental tank gauge on head	VM0031
Hot and cold transom shower	VM0016
Salt water wash down system fore and aft	VM0017
Fresh water wash down forward	VM0032
Shore water system with filter (aft starboard entrance)	VM0043
Single Seagull water purifier on ice maker	VM0034
Single Seagull water purifier on galley cold water	VM0034

Standard yacht has a sport yacht white hull and deck with cherry interior. See individual model specification and equipment list for complete details. F.O.B. South Casco, Maine. Special option requests must be received six weeks prior to molding of the hull to assure availability.

Sabre does not guaranty the durability of dark gelcoats. Hulls built with dark colors will fade more quickly than light colors, will show more mold imperfections and scratches amd can cause the laminate to post cure, causing cosmetic distortion of the surface. These deformations are not structural in nature and are therefore not covered by the Sabre Limited Warranty.